
**Hot Item:**


Repeated failure of SMPS or 12amp fuse on SMPS.

Replace Y main when replacing SMPS where the 12amp fuse is open.

**Firmware version: 1022**  
**Resolves HDMI video flicker**

**No Service Bulletins**

Version	Parts No	Short Description
ALL	BN44-00175A	SMPS
ALL	BN94-01187D	Main PCB
ALL	BN96-04802A	Blue light
ALL	BN96-04809H	Function & IR PCB
KL01	BN96-04862A	X Main
KL01	BN96-04863A	Y Main
KL01	BN96-04864A	Y - Upper
KL01	BN96-04865A	Y - Lower
KL01	BN96-04866A	Logic Main PCB
KL01	BN96-04867A	Buffer E
KL01	BN96-04868A	Buffer F
KL01	BN96-04869A	Buffer G
ALL	BN96-06284E	A/V Side PCB
KR02	BN96-06811A	X Main
KR02	BN96-06812A	Y Main
KR02	BN96-06813A	Y - Upper
KR02	BN96-06814A	Y - Lower
KR02	BN96-06815A	Logic Main PCB
KR02	BN96-06816A	Buffer E
KR02	BN96-06817A	Buffer F
ALL	BN67-00192A	Glass EMI Filter
KL01	BN96-04761A	Panel
KR02	BN96-06123A	Panel
ALL	BN96-05442B	Front Cover
KL01	BN96-05443B	Rear Cover
KR02	BN96-05443H	Rear Cover
ALL	BN96-05449A	Stand Base
ALL	BN39-00843C	LVDS Cable
ALL	BN40-00107A	Tuner
ALL	BN96-05587A	Speaker
ALL	BN96-05588A	Speaker
ALL	BN96-05589A	Speaker
ALL	BN96-05590A	Speaker
ALL	3903-000144	Power Cord
ALL	BN59-00599A	Remote





## Support Sheet

## To do list:

Option bytes should always be verified before and after the repair.  
 Quick links listed below for training, triage and Help.

## Option Byte setting

## Saffron 84 Series

TV Model	Side Label Version	S/W Version	Parts Code									
			SMPS	Main Board	Module	X-Main	X-Main Scan Buffer	Y-Main	Y Main Scan Buffer	Logic B'd	E Buffer	F Buffer
FPT5084X/XAA	KL01	T-SAFAUUSC-1021	BN44-00175A	BN94-01187D	BN96-04761A	BN96-04862A	-	BN96-04863A	UPPER : BN96-04864A LOWER : BN96-04865A	BN96-04866A	BN96-04867A	BN96-04868A

Training  
 Plus One

<http://my.plus1solutions.net/clientPortals/samsung/>

Help  
 GSPN

[http://service.samsungportal.com/EP/web/portal/jsp/EP\\_Default1.jsp](http://service.samsungportal.com/EP/web/portal/jsp/EP_Default1.jsp)